UNCLASSIFIED

AD NUMBER

AD396877

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited

FROM:

Distribution authorized to U.S. Gov't. agencies only; Foreign Government Information; AUG 1965. Other requests shall be referred to British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008.

AUTHORITY

DSTL, ADM 302/395, 17 November 2008; DSTL, ADM 302/395, 17 November 2008

CONFIDENTIAL

AD 396877

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA, VIRGINIA



NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

NOTICE:

THIS DOCUMENT CONTAINS INFORMATION

AFFECTING THE NATIONAL DEFENSE OF

THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18,
U.S.C., SECTIONS 793 and 794. THE

TRANSMISSION OR THE REVELATION OF
ITS CONTENTS IN ANY MANNER TO AN
UNAUTHORIZED PERSON IS PROHIBITED

BY LAW.

UNANNOUNCED

CONFIDENTIAL

NSTIC/Chips/ 63

Part 3

5 Par

U.D.C. No

620-19:620-18: 623-946-77 A.U.W.E. Tech Note 192/65

AUGUST 1965

Part 3

A.U.W.E Toch Note 192/65 3 9 68 7 7

A CORROSION STUDY ON MATERIALS FOR USE WITH PHOSPHORUS & SULPHUR

BEARING FUELS

Part 3

ANE 9 1966

بالملان

BY H. GOLDIE

AU MO. DDC FILE COPY

U.S. GOVERNMENT ORGANIZATIONS ONLY

This document is the Property of H.M. Government. The officer to whom it is issued is personally responsible for its safe custody and for ensuring that no part of its contents becomes known to unauthorised persons.

Any person other than the authorised holder who finds or otherwise obtains possession of this document should post it, together with his name and address to the Chief Scientist, Admiralty Underwater Weapons Establishment, Portland, Dorset, Postage will be refunded.

ADMIRALTY UNDERWATER WEAPONS ESTABLISHMENT PORTLAND

EXCLUDED FROM AUTOMATIC REGRAPING; DOD DIR 5200.10 BOES NOT APPLY

ACCESS!	ON for	
OFETTI DBC UPARROW 31116	WHITE SECT BAFF SECT NGED	
	TIDIFAVALLABILITY	CODES
BIST.	AVAIL and/or ST	PEGIAL
13		

The views expressed herein do not necessarily represent the considered opinion of the issuing establishment and must not be taken to define Ministry of Defence (Naval) or Departmental policy.

AMENDMENTS

N	UMBER	2	3	4	5	6	7	8	9	10
	DATE `									

Ittention is drawn to the penalties attaching to any infraction of the Official Secrets Act

U.D.C. No. 620 19:620.18:

A.U.V.E. Technical Note 192/65

14) AUWE-TN-192/65-

CORROSION STUDY ON MATERIALS LOR USE WITH PHOSPHORUS AND SULPHUR BEARING FUELS.

MINAPION OF CONDUSTION CHAIRER COMPONENTS CC 1

Drechnical note

(10) H. Goldie.

-000-

(18) NSTIC (19) 06176/66

This document contains information affecting the Mational Defense of the United States within the meaning of the Espionage Laws, Title 18, U. S. C., Section 793 and 794. Its transmission or the revelation of its contents in any wanner to an unauthorsied Herrorh is prohibited by law."

									Cop	y ivo	2.
D.W. Irog. (N)	• • •	•••	• • •	•••	• • •	• 2 •	• • •	•••		1	
J.1. Lat. (II)	• • •	•••	•••	•••	•••	• • •	• • •	•••		2	
0.2.7.5.6.	• • •	•••	•••	• • •	• • •	•••	• • •	•••		3	
D.N.P.R.	•••	•••	•••	•••	• • •	•••	• • •	• • •		4.	
Supt.,L.	•••	• • •	•••	•••	•••	• • •	• • •	• • •		5	
Supt., C.D.L.	•••	•••	•••	•••	•••	***	• • •	• • •		ó	
Sec. Heat Resista	ant lia	terials	Comm	ittee !	I.S.M.	I.T	•••	• • •	7	to	56
N.D. Committee fo											
Machinery Sub-Con	mitte	э	•••	• • •	600	• • • •	•••	•••	57	to	86
N.S.T.I.C	• • •	• • •	• • •	•••	6 • r	•••		• • •	87	to	115

(G by 2. U.L. Z. 1965

CONTENTS

		Page No.						
Précis		1						
Conclusions		1						
Recommendatio	ons for Future Work	2						
Introduction		3						
Examin tion 1	: High Tensile Steel Screw	3						
Examination 2	2: Stainless Steel Thermocouple	رَ						
Remination 3	3: Dilucnt Ring Test Run 28	4						
Examination 4	: Supersonic Nozzle Test Run 32	5						
Examination 5	Experimental Blade Rod used as 'Control' ~ Test Run 39	6						
ILLUSTRATIONS Sections from Components exposed to PPS Combustion Products								
Tique								
1 end 2	High Tensile Screw.							
3	Steinless Steel Thermocouple.							
h to 8	Diluent Ring Test Rum 28.							
	Microenelysis - Section Dil Ring M-Ray Images Ni, Cr, Cu, Si, P.							
14 and 15	Supersonic Nozzle Gold Plates.							
16 to 19	Exp. Blade Test Run 39.							
20 and 21	Eilver Steel Rod Test Run 39.							
	Microanelysis Silver Steel Rod. Llectron image scale. X-Ray images Fe and P.							

A COPROSION STUDY ON MATERIALS FOR USE TITE PHOSPHORUS IND SULPHUR BE RING FUELS

PART THREE

EXAMINATION OF COMBUSTION CHARB R COMPONENTS

PRICIS

- 1. The protection offered by oxide films and corrosion product during the static laboratory tests was not reproducible under combustion conditions. The action of fast-moving gas and/or liquid droplets of metaphosphoric acid in the combustion system led to extremely high metal loss by erosion as well as corrosion.
- 2. This part of the report includes a microscopical study of sections taken from demaged components after exposure to phosphorus-phosphorus sesquisulphide (PPS) combustion products. The examinations were carried out at various stages of the PPS programme, principally to give some indication as to the cause of damage.
- 3. The poport shows that damage can be caused by
 - (a) corrosion and erosion of materials by liquid phosphoric acid contained in the moving combustion stream. Products of the reaction were found to be metallic metaphosphates and hydrogen.
 - (b) corrosion and crosion of materials by phosphoric acid vapour,

the products of reaction being phosphides or phosphide eutectics depending on the distribution of phosphorus.

CONCLUSIONS

- He The mechanisms of attack associated with metrls when exposed to the phosphorus-phosphorus sesquisulphide (PFS) combustion gases were found to be similar to those shown by metals when exposed to the synthetic combustion atmospheres used for the static laboratory tests.
- 5. The protection offered by adhering corrosion product during static tests was not reproducible under combustion conditions. The action of fast-moving gas and or liquid droplets of metaphosphoric acid in the combustion chamber led to high loss of metal by erosion as well as corrosion.
- 6. Letaphosphoric acid vapour was considered responsible for the production of metallic phosphides. Combustion trials lasted only a matter of minutes. Even so, the metallic scales were found to contain sufficient phosphorus to support phosphide formation.
- 7. The short periods of exposure led to uneven distribution of phosphorus in the attacked areas and eutectic distribution was not so characteristic as compared with the results from the much longer exposures associated with laboratory tests.

RECOILINDATIONS FOR FUTURE WORK

- 8. Future work should include the use of
 - (a) micro-enalysis techniques to identify surface and grain boundary reactions of alloys when exposed to the PPS combustion products,
 - (b) M-ray diffraction techniques to identify deposits and corrosion products formed.

Tuture work should also include

- (c) combustion trials using test samples of metals which form solid scales or corrosion product up to 1500°C e.g. No, Ta, Ir, Ii.
- (d) Phosphorus-phosphorus sescuisulphide combustion trials using test samples of conventional materials costed with non metallic deposits e.g. aluminia, silicon nitride and also with the above resistant metals and their alloys using vapour deposition or electro-deposition as appropriate.

INTRODUCTION

- 9. In addition to corrosive atmosphere and working temperature, factors such as flow rate of working fluid, non-equilibrium associated with practical combustion conditions and pressure within the system, must be included in the overall assessment of material or component damage.
- 10. The protection offered by adhering corrosion product during the static laboratory tests was not reproducible under practical combustion conditions. The corrosion product when formed was readily removed by the action of the gas stream. This affect led to conjoint attack, i.e. erosion and corrosion.
- 11. The report is based on a microscopical study of the surface and structural characteristics of combustion chamber components after high-temperature exposure to the phosphorus-phosphorus sesquisulphide (PPS) combustion products. The examinations were carried out at various stages of the FTS programme principally to give some indication as to the case of damage.

EX/MINATION 1: HIGH TENSILE STELL SCREEN, CADMINE PLATED

Pranination

- 1. The head and last seven threads had been affected, the appearance being that of an eroded surface (Figure 1). The circumference of the head had been reduced and the socket enlarged to such an extent that the wall corresponding to one side of the hexagon had been removed almost completely (Figure 2).
- 13. Efferoscopical examination showed the material to have a uniform martenaitic type structure. A hardness survey along the length of the serew gave DFF 460 maximum, DFN 440 minimum indicating the absence of overheating or any appreciable temperature gradient during the trial. I thin scale covered the head and damage threads of the serew. There was no evidence of intercrystalline attack.

Conclusion

11/2. It is considered that the set serew had suffered damage by corresion/erosion. Irosion by flowing seid probably contributed the major part of the damage.

EXAMINITION 2: STAINLESS STEEL THURMOCOUFLE

Deamination

15. Figure 3 shows that an area of the probe approximately 0.7 inch long and half the circumference wide had a highly-polished appearance. Approximately at the centre line of this area and adjacent to the tip of the probe a longitudinal hole had been formed.

- 16. Further examination revealed that the wall thickness had been considerably reduced at the polished area, the area of maximum reduction resulting in a hole. The down stream side of the probe appeared heavily pitted, probably due to a form of abrasive blasting by extremely fine combustion product particles.
- 17. The thermocouple probes were not sectioned for microscopical examination.

Conclusion

٨.

18. It is considered that failure of the thermocouple probe was principally due to erosion caused by fine combustion product in the gas stream. The flow of liquid droplets of phosphoric acid would also produce a polished and rounded surface.

TEST RUN NO. 28

Test Conditions

Euration of hot run - 130 seconds

From final gas temperature - 700°C

Fuel/Oxident Ratio - 5 per cent fuel rich.

Commination

- 19. The mouth and bore of the diluent ring were covered with a green deposit of inorganic phosphete. The rear face was partially covered with a dark adherent metallic scale. The scale was subsequently found to be magnetic. The conical approach wall and areas adjacent to the water injection holes had been badly damaged (Figure 4). The rear face also suffered damage (Figure 5), the corrosion/erosion pattern being dependent on the location of the water injection holes.
- 20. Microscopical examination of sections cut from
 - (a) conical wall approach
 - (b) areas adjacent to the injection holes and rear face

showed evidence of a metallic scale containing entrapped particles of phosphote (Figure 6). Areas within the scale showed dendritic characteristics associated with the freezing of liquid metal (Figure 7). Subsequent etching revealed the phosphorus rich character of the metallic scale but a definite entectic phase could not be clearly resolved (Figure 8).

21. These scaples were examined using the Electron Beam X-Ray microchalyser. The results are detailed below. X-ray images showing the distribution of Fe, Ni, Cr, Cu, S and P at the scale/case metal interface are shown in Figures 9 to 13 respectively.

- 22. The examination gave the following information. A slow scan for nickel across a line in the sample indicated that the nickel concentration increased in the plain areas as compared to those areas in which a cutectic type structure appeared. The concentration of iron in these plain areas was also found to be high while that of phosphorus appeared to be lover.
- 23. The concentration of chromium in the phosphorus-rich region or scale was low and no marked concentration gradients were found in the stainless steel at the base metal/scale interface.
- 24. Ippreciable quantities of copper were found in the scale generally evenly distributed. Small quantities of sulphur were detected mainly segregated at the metal/scale interface. The approximate concentrations of Fhosphorus, Copper and chromium in the scale were estimated to be 10; 4. and 3 respectively. The attack on monel metal components up stream of the cilient ring can explain the presence of liquid copper phosphice entectic entrapped in the combustion stream and subsequent presence of this metal in the attacked surfaces of an alloy component originally free from copper.

Conclusions

- 25. It is considered that the damage to this component was caused principally by high-temperature corrosion from phosphorus compounds.
- 26. The microscopical examination revealed the presence of surface phosphides and phosphide eutectics. Micro-enalysis confirmed the presence of phosphorus in sufficient quantity to support eutectic phosphide formation.
- 27. Those findings suggest that during the extremely short exposure (130 seconds) the surface of the diluent ring exceeded 950°C, i.e. the minimum temperature for outectic formation. Liquid acid attack may have contributed to the total damage suffered by the component but this effect would only be of minor importance compared with phosphide formation.

EXAMINATION NO. 4: TEST RUN NO. 32

Component - Supersonic Nozzle.

Haterial - HV58J Stainless Steel protected with 0.003 inch gold.

Test Conditions - Duration of trial, 120 seconds. Mean final product gas temperature, 400°C Fuel/Oxident ratio: 5% fuel rich.

littemination

20. The upstream surface of the nozzle was covered with a green deposit of metaphosphate (Figure 14). The throat area showed evidence of coating failure due to blistering. The exhaust area was badly blistered and showed deposits of solid corrosion product. The rear face of the nozzle was also demaged (Figure 15).

29. Hetallurgical examination revealed that the blistering may have resulted from the effect of heat on poor quality plating. Irregular pile up of gold 0.030 inch thick appeared on the downstream surfaces. Areas were visible where the gold had been completely removed leaving the base metal exposed to the combustion gases.

Conclusions

- 30. The examination failed to show positive evidence of direct chemical reaction between combustion phases and the protective gold. It is considered that the damage to this component was caused by
 - (a) chemical attack of the base metal through cracks and porce in the protective coating.
 - (b) the action of the fast moving gas/liquid acid stream over the soft gold layer.
- 31. However it is difficult to account for the large pile up of gold on the downstream surfaces unless the temperature within the chamber was higher than 400°C.

EXAMINATION NO. 5: TEST RUN NO. 39

Components

- (a) Experimental Blade: IN58J Stainless Steel.
- (b) Circular Rod used as 'Control': Silver Steel.

Test Conditions

- (a) luration of trial: 123 seconds.
- (b) Hean final gas temperature: 1000°C.
- (c) Fuel/Oxident Ratio: 5; Fuel Rich.
- (d) Components exposed to the jet efflux from the combustion chamber.

Stainless Steel Blade

- 32. The leading edge of the blade suffered severe erosion while the centre had been virtually removed leaving a vee shaped groove. The apen of the groove limost reached the opposite edge of the blade (Figure 16).
- 33. Microscopical examination showed an almost continuous non-adhering metallic scale at the damaged surfaces (Figure 17). Certain areas showed evidence of intercrystalline attack and deposits of metaphosphate associated with the metallic scale, (Figure 18). Subsequent etching revealed that the scale contained eutectic phosphides (Figure 19).

Conclusions

34. It is considered that the damage to this component was caused by reaction between base metal and phosphoric acid (probably metaphosphoric vapour) ultimately resulting in the formation of low melting point phosphides. These compounds once formed would be rapidly removed by the action of the gas stream.

Silver Livel used as "Control"

- 35. The tip of the exposed end had been completely removed while the remainder appeared to be covered with a dark metallic deposit. This deposit was subsequently found to be extremely hard and porous (Figure 20).
- 36. Pheroscopical examination of a longitudinal section cut from the rod revolled a rapid change in microstructure between unexposed and exposed areas. The former showed a spheroidised structure related to that of the original condition of the material. The latter was found to consist of coarse partensite, a structure normally associated with heating to temperatures above the upper critical followed by rapid cooling. The deposit was found to contain primary dendrites of martensite in a fine cutectic matrix. Figure 21 shows the structure after etching at the steel/deposit interface.
- 37. Electron Beam X-Ray microanalysis of the deposit showed that the iron content of the scale was 10% less than that of the base metal. The phosphorus and copper contents were found to be approximately 1%. Figure 22 shows the electron image of the area selected for analysis. Figures 23 and 2% are X-ray images for phosphorus and iron respectively.

Conclusions

- 38. Although phosphorus was found in the deposit, the cutectic matrix was considered to be essentially transformed Ledeburite. This structure probably resulted from a temperature exceeding the equilibrium liquilus i.e. for silver steel approximately 1350°C.
- 39. The porous nature of the deposit may have resulted from a gas-forming reaction similar to that of "carbon boil" in steel making. This would require removal and oxidation of carbon from the silver steel/deposit to form carbon monomide by the reaction

40. The temperature at the top of the rod may also have been raised above the gas stream by combustion of iron to phosphide.

CONFIDENTIAL HIGH TENSILE SCREW




FIG I





X 3.5



X 3.5

CONFIDENTIAL

STAINLESS STEEL THERMOCOUPLE




FIG 3

CONFIDENTIAL TEST RUN-28 EN58J DILUENT RING




FIG 4
UPSTREAM FACE



FIG 5
DOWNSTREAM FACE

CONFIDENTIAL


CONFIDENTIAL TEST RUN No. 28 DILUENT RING

TEST RUN No. 28
DILUENT RING



FIG 6

UNETCHED



CONFIDENTIAL

UNETCHED

TEST RUN-28
DILUENT RING





FIG 8

ETCHED 10% OXALIC ACID ELECTROLYTIC


TEST RUN - 28 STAINLESS STEEL DILUENT RING MICRO ANALYSIS



X-RAY IMAGE-NICKEL


FIG 9

FIG 10



X-RAY IMAGE CHROMIUM


TEST RUN-28 STAINLESS STEEL DILUENT RING MICRO ANALYSIS



X-RAY IMAGE COPPER


FIG II

FIG 12



X-RAY IMAGE SULPHUR

TEST RUN - 28 STAINLESS STEEL DILUENT RING MICRO ANALYSIS




X-RAY IMAGE PHOSPHORUS

TEST RUN-32

SUPERSONIC NOZZLE - GOLD PLATED

FIG 14




UPSTREAM FACE

FIG 15



DOWNSTREAM FACE

TEST RUN-39 EXPERIMENTAL TURBINE BLADE EN58J PLACED IN EFFLUX FROM NOZZLE




X5

TEST RUN-39 EXP BLADE-EN58J



X500 UNETCHED



UNETCHED

TEST RUN-39
EXP BLADE-EN58J




FIG 19

X 500

ETCHED-10% OXALIC ACID ELECTROLYTIC

TEST RUN-39 CONTROL ROD - SILVER STEEL





FIG 20


X5

UNETCHED



X 250





CONFIDENTIAL

U.K. ADSTRACT

() Country of Origin

UNITED KIEGDON

(B) Listablishment of origin with short address

Admiralty Underwater Weapons Establishment, Portland.

(C) Title of Report

A Corresion Study on Materials use with Phosphorus and Sulphur Bearing Fuels

Part Three

Examination of Combustion Chamber Components

(D) Luthor

H. Goldie

(E) Pages and Figures

9 pages ((i) - (ii) (1 - 7))
24 figures.

(F) Date

August, 1965

(3) Originator's Reference

Technical Note 192/65

(H) Security Grading

CONFIDERTIAL

(J) .bstract

The protection offered by oxice films and adhering corrosion products during static tests (see Parts 1 and 2) was not reproducible under combustion conditions. The action of fast-noving gas and/or liquid droplets of metaphosphoric acid led to extremely rapid and high metal loss in the combustion system by erosion as well as corrosion.

This report describes the microscopical and surface characteristics of combustion components after exposure to the phosphorus—phosphorus sesquisulphide (PPS) combustion products. The examinations were carried out at various stages of the programme, principally to give some indication as to the cause of damage.

Dotecheble Abstract Cards

These abstract cards are insarted in K.U. w.B. reports and notes for the convenience of librarians and others the need to maintain an information index

CONFIDENTIAL A.U.H.E. Technical Hote 192/65 August, 1965 H. Goldie

620-19:620-18:

620.19:620.18:

for use with Phosphorus and Culphur Bearing Fuels A Corrosion Study on Materials

Port Three

Examination of Combustion Chamber Components

The protection offered by oxide films and adhering corrosion products droplets of metaphosphoric acid led to extransly rapid and high retal loss combustion conditions. The action of fast-moving gas and/or liquid during static tests (see Parts 1 and 2) was not reproducible under in the combustion system by erosion as well as corrosion.

This report describes the microscopical and surface characteristics sesquisulphide (PPS) conbustion products. The examinations were cerried of combustion components after exposure to the phosphorus-phosphorus out at various stages of the programme, principally to give some indication as to the cause of darmge.

A.U.W.E. Technical Note 192/65

August, 1965 H. Goldie

A Corrosio. Study on Materials

for use with Phosphorus and Sulphur Bearing Fuels

Part Three

Examination of Combustion Chamber Components

The protection offered by skide films and adhering correston products droplets of netaphogenoric acid led to extremely rapid and high netal loss combustion conditions. The action of fast-moving gas and/or liquid (ras not reproducible under In the combustion system by erosion as well as corresion. during static tests (coeff

This report describes the microscopical and surface characteristics sesquisulphide (PPS) combustion products. The exeminations were carried of combustion components after exposure to the phosphorus-phosphorus out at warious stages of the programme, principally to give some Indication as to the cause of damage.

CONFIDENTIAL

A.U.W.E. Trehnical Note 192/65 August, 1965 H. Goldie

623.946.77

or use with Phosphorus and Sulphur Eeering Fuels A Corrosion Study on Materials

Part Three

Exanimation of Combustion Chamber Couponents

The protection offered by oxide films and adharing corrosion products droplets of metaphosphoric acid led to extremely rapid and high metal loss combustion conditions. The action of fast-moving gas and/or liquid during static tests (see Parts 1 and 2) was not reproducible under in the combustion system by erosion as well as corrosion.

sesquisulphide (PPS) combustion products. The examinations were carried This report describes the microscopical and surface characteristics of combustion components after exposure to the phosphorus-phosphorus out at warious stages of the programme, principally to give some Indication as to the cause of damage.

A.U.W.E. Technical Note 192/65 August, 1965 H. Goldie

620.19:620.18: 1.95°F

520.19:620.18: 623.946.77

for use with Phosphorus and Sulphur Bearing Fuels A Corrosion Study on Materials

Part Three

Examination of Combustion Chamber Components

The protection offered by oxide films and adhering corrosion products droplets of metaphosphoric acid led to extremely rapid and high metal loss combustion conditions. The action of fast-moving gas and/or liquid during static tests (see Parts 1 and 2) was not reproducible under in the corbustion system by erosion as well as corrosion.

of combustion components after exposure to the phosphorus-phosphorus sesquisulphide (PFS) combustion products. The examinations were carried This report describes the microscopical and surface characteristics out at warfous stages of the programme, principally to give some Indication as to the cause of damage.



Information Centre Knowledge Services [dst] Porton Flown, Salishury B948 NP4 64Q 22060-6218 Tot. 01980-613238 Fax 01980-613270

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: AD396877

Date of Search: 17 November 2008

Record Summary: ADM 302/395

Title: A corrosion study on materials for use with phosphorus and sulphur bearing fuels: pt 3

Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years Former reference (Department) AUWE Technical Note 192/65 Pt 3 Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967.

The document has been released under the 30 year rule.

(The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as <u>UNLIMITED</u>.